

Technical Service Bulletin

GROUP	NUMBER			
AUTOMATIC TRANSMISSION	13-AT-005-1			
DATE	MODEL			
MARCH 2013	Elantra Sedan (HD) Elantra Touring (FD)			

SUBJECT: AUTOMATIC TRANSAXLE HARSH AND/OR DELAYED UPSHIFT – GDS ANALYSIS

This TSB supersedes TSB 13-AT-005 to revise the Op Code

Description:

This procedure uses the GDS to analyze shift performance for the 2007~10 Elantra Sedan and 2009~12 Elantra Touring.

Model Years	Model
2007~10 2009~12	Elantra (HD) Elantra Touring (FD)

WARRANTY INFORMATION - No Trouble Found (NTF):

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
2007~10 Elantra Sedan 2009~12 Elantra Touring	45000RQ0	GDS Operation	0.3	00268 See Parts Catalog	N26	C11

WARRANTY INFORMATION – Automatic Transaxle replacement

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
2007~10 Elantra Sedan 2009~12 Elantra Touring	45000R00	Replace auto transaxle	4.0	00268- See Parts Catalog	N26	C11
	45000RQ0	GDS Operation	0.3		N26	C11

SERVICE PROCEDURE:

- 1. Check the ATF level when the engine is idling in "N" according to TSB 06-40-016. Adjust the ATF level as needed.
- Reset and relearn the adaptive values according to TSB 12-AT-017.

SUBJECT: AUTOMATIC TRANSAXLE HARSH AND/OR DELAYED UPSHIFT - GDS ANALYSIS

- 3. Compare to a similar model and year vehicle. If the shift delay is:
 - Same as comparison vehicle: Return the vehicle to the customer
 - Longer than the comparison vehicle, continue with the diagnosis.
- 4. Attach the GDS and check for Diagnostic Trouble Codes in both the "Engine" and "Automatic Transaxle" menu. If DTC are found, repair according to the appropriate TSB or shop manual.
- 5. Attach the GDS and select the following:
 - VIN and "A/T"
 - "Current Data"
 - > Shift position
 - Pressure Control Solenoid A duty
 - Pressure Control Solenoid B duty
 - Pressure Control Solenoid C duty
 - On/off solenoid duty



Ask an assistant to drive the vehicle as you monitor the GDS.

- 6. Drive the vehicle and verify the condition:
 - Accelerate the vehicle and shift from 1-2-3-4 at 25~50% throttle (TPS).
 - Select "Record" (on top right of screen)
 - Select "PC Record" (on left of screen) and save the file.


TSB #: **13-AT-005-1** Page 2 of 5

REVIEW THE GDS DATA:

1-2 UPSHIFT:

- Open the GDS program and select:
- VIN and "A/T"
- "Flight Record" and "Data Review"
- Select "Items List" (top right of screen) and select: "Shift Position", "Pressure control solenoids A, B & C" and "On/off solenoid".
- Click the "+" or "-" buttons to choose 0.5 sec./Div. or less.
- Move the cursor to the start of the shift and "Left click".
- Move the cursor to the end of the shift and "Right click".
- Read the Pressure Control Solenoid B elapsed time at the top right of the screen. If the 1-2 shift requires more than 2.0 seconds, replace the transaxle.

NOTE: The Solenoid B elapsed time is important; the shape of the graph is not.




TSB #: 13-AT-005-1 Page 3 of 5

2-3 UPSHIFT:

Open the GDS program and select:

- VIN and "A/T"
- "Flight Record" and "Data Review"
- Select "Items List" (top right of screen) and select: "Shift Position", "Pressure control solenoids A, B & C" and "On/off solenoid".
- Click the "+" or "-" buttons to choose 0.5 sec./Div. or less.
- Move the cursor to the start of the shift and "Left click".
- Move the cursor to the end of the shift and "Right click".
- Read the Pressure Control Solenoid A elapsed time at the top right of the screen. If the 2-3 shift requires more than 2.0 seconds, replace the transaxle.

NOTE: The Solenoid A elapsed time is important; the shape of the graph is not.




TSB #: 13-AT-005-1 Page 4 of 5

3-4 UPSHIFT:

- Open the GDS program and select:
- VIN and "A/T"
- "Flight Record" and "Data Review"
- Select "Items List" (top right of screen) and select: "Shift Position, Pressure control solenoids A, B & C and On/off solenoid.
- Click the "+" or "-" buttons to choose 0.5 sec./Div. or less.
- Move the cursor to the start of the shift and "Left click".
- Move the cursor to the end of the shift and "Right click".
- Read the Pressure Control Solenoid B elapsed time at the top right of the screen. If the 3-4 shift requires more than 2.0 seconds, replace the transaxle.

NOTE: The Solenoid B elapsed time is important; the shape of the graph is not.



TSB #: **13-AT-005-1** Page 5 of 5