

## Service Bulletin

File in Section: 06 - Engine

Bulletin No.: 08-06-01-006D

Date: May, 2013

# **TECHNICAL**

Subject: Engine Squealing Type Noise on Start-up or Vibration

Models: 2007 Buick Rendezvous

2007-2008 Buick Terraza 2007 Chevrolet Monte Carlo 2007-2009 Chevrolet Uplander 2007-2010 Chevrolet Malibu 2007-2011 Chevrolet Impala 2007-2009 Pontiac Montana SV6

2007-2010 Pontiac G6 2007-2008 Saturn Relay 2007-2009 Saturn AURA 2007-2010 Saturn VUE

Equipped with 3.5L or 3.9L Engine (VINs N, K, R, W, 1, 3, 8 – RPOs LZ4, LZE, LZ8, LGD,

LZ9, LZG, LX9)

This bulletin is being revised to add the 2008-2011 model years to the applicable vehicles. Please discard Corporate Bulletin Number 08-06-01-006C.

#### Condition

Some customers may comment on a squealing type noise coming from the engine compartment on start-up. Others may comment about an engine vibration.

#### Cause

The outer ring on the crankshaft balancer may be slipping on the center hub.

#### Correction

Inspect the crankshaft balancer to see if the outer ring is slipping on the center hub. If this condition is found, replace the crankshaft balancer using the applicable one listed in the parts catalog. Refer to Crankshaft Balancer Replacement in SI.

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4063290	Crankshaft Balancer Replacement	Use Published Labor Operation Time