

Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



MAZDA

© 2014 Mazda Motor of America, Inc.

Subject: TOMTOM NAVIGATION FUNCTIONALITY CONCERNS AFTER MSP42	Bulletin No: 09-020/14
	Last Issued: 04/29/2014

BULLETIN NOTE

- This bulletin supersedes the previous bulletins 09-020/14 issued on 04/07/14. The WARRANTY INFORMATION has been revised.
- Changes are noted below beside the change bar in Red.

APPLICABLE MODEL(S)/VINS

- 2013-2015 CX-5 vehicles (with factory or dealer installed TomTom navigation)
- 2013-2014 CX-9 vehicles (with factory or dealer installed TomTom navigation)
- 2013-Mazda3 vehicles (with factory or dealer installed TomTom navigation)
- 2014-2015 Mazda6 vehicles (with factory or dealer installed TomTom navigation)

DESCRIPTION

Some vehicles may experience the symptoms mentioned below, which can be fixed with the latest software update (Version 10.852 or later).

- Vehicle icon jumps around or vibrates.

CAUTION: DO NOT use the factory reset for retail vehicles. Otherwise, personal settings (such as display and sound adjustments) will be lost, including favorites information.

Customers having any of these concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Update the TOMTOM NAVIGATION with software version 10.852 or later using the instructions in TSB 09-010/14 - MAZDA SERVICE PROGRAM (MSP42) - TOMTOM NAVIGATION SYSTEM UPDATE.
3. Verify repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical—including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

SPECIAL CLAIM SUBMISSION INSTRUCTION:

- Perform an eMDCS Warranty Vehicle Inquiry on the VIN.
- View the status of MSP42
 - If MSP42 for the vehicle shows status of "Open" input the warranty claim using MSP42 OPEN information below. This will close the MSP42.
 - If MSP42 for the vehicle shows status of "Closed" input the warranty claim using MSP42 CLOSED information below.
 - If the vehicle is not flagged for MSP42, input the warranty claim using MSP42 CLOSED information below.

	MSP42 OPEN	MSP42 CLOSED
Warranty Type	A	A
Process Number	AD056A	--
Symptom Code	99	61
Damage Code	99	9H
Part Number Main Cause	7777-SP-J41	GJS1-66-EZ0B
Quantity	0	0
Operation Number / Labor Hours:	XXK39XFX / 0.3 Hrs.	XXK67XFX / 0.3 Hrs.