



Service Bulletin

File in Section: -

Bulletin No.: PIT5186A

Date: August, 2013

PRELIMINARY INFORMATION

Subject: Rear Video Screens May Not Turn On

Models: 2012-2014 Cadillac Escalade Models
2012-2014 Chevrolet Suburban, Tahoe
2012-2014 GMC Yukon and Yukon XL Models
Equipped with Single Rear Video Screen (RPO U42) or Dual Rear Video Screens (RPO DNU)

This PI was superseded to update recommended field models and model years. Please discard PIT5186.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customers may comment that one or both of the roof mounted video screens will not turn on.

Recommendation/Instructions

Please check X206 and X306 for terminal damage or loose connections. Repair or replace any terminals with concern, power off vehicle for 5 minutes, and validate repairs by testing video screen functionality.

(X206 location- RH A-pillar harness to I/P harness (Y91) or I/P extension harness (except Y91) top right side of the I/P under defroster deflector near center)

(X306 location- Headliner harness to right A-pillar harness front center roof behind the left side of the overhead console assembly)

Note: Connector X306 can be accessed by removing the overhead console only, headliner removal is not required.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.