

WK

NUMBER: 21-010-14

GROUP: Transmission and Transfer Case

DATE: April 01, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

Transmission Torque Management Enhancements While in Reverse

OVERVIEW:

This bulletin involves replacing the transmission control module with a revised part.

MODELS:

2013

Grand Cherokee SRT8 - Australia Market Only

NOTE: This bulletin applies to SRT8 vehicles sold in Australia only.

SYMPTOM/CONDITION:

Customers may indicate that the engine does not have enough power to back a trailer up a steep grade. In addition, they may also indicate that the transmission shifts too early during acceleration while turning.

DIAGNOSIS:

A revised transmission software calibration improves the transmission torque management in reverse and while turning.

If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	05150891AB	Module, Transmission Control

REPAIR PROCEDURE:

- Replace the transmission control module. Refer to DealerCONNECT>Service>TechCONNECT>Service Info>08 - Electrical>8E -Electronic Control Modules>MODULE, Transmission Control>Removal/Installation for additional information.
- Perform the adaptation procedure. Refer to DealerCONNECT>Service>TechCONNECT>Service Info>08 - Electrical>8E -Electronic Control Modules>MODULE, Transmission Control>Standard Procedure>ADAPTATION - 3.6L/6.4L GAS/3.0L DIESEL VEHICLES for additional information.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-19-05-90	Module, Transmission Control (TCM) - Replace (2 - Skilled)	2 - Automatic Transmission	1.0 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------