

074 (Rev 1, 9/13/2016)	August 2016
NUMBER	DATE
СНА	Multiple Models
GROUP	MODEL

TECHNICAL SERVICE BULLETIN

SUBJECT:

MDPS FLEXIBLE COUPLING REPLACEMENT

***** NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area.

This bulletin is issued to provide information about the replacement of the flexible coupling in the MDPS motor of some vehicles which might experience a "knock" noise originating from the MDPS, when moving the steering wheel to right or left when the vehicle is stopped. This is caused by premature wear of the flexible coupling in the MDPS motor. If any "knock" noise from the MDPS occurs, replace the affected flexible coupling only with an improved one, following the Replacement Procedure below.

Please note that Replacement Procedures 1, 2 and 3, as shown below, vary depending on the model. Calibration Procedures only apply to Replacement Procedures 1 and 3. For reference, there are 2 types of torque sensors to detect revolution and torque in the MDPS system. One is the optical type which detects when light is transmitted and the other is the magnetic type which detects changes in polarity.

Procedure	Model/Year	Applicable Production Range	Replacement Part
1	Forte (TD) / 2012~2013	From Jan. 05, 2012 ~ Mar. 31, 2013	
2	Soul (AM) / 2010~2013	From Sep. 01, 2009 ~ Aug. 15, 2013	She
Z	Forte (YD) / 2014	From Jan. 7, 2013 ~ Dec. 18, 2013	200
3	Cadenza (VG) / 2014	From Feb. 01, 2013 ~ Apr. 19, 2014	

File Under: <Chassis>

Circulate To:Image: Circulate To:Image:

Page 2 of 16

SUBJECT:

MDPS FLEXIBLE COUPLING REPLACEMENT

Replacement Procedure 1: This procedure applies to Forte (TD) models.


1. Remove the MDPS unit by referring to the applicable procedure on KGIS.


***** NOTICE

Before removing the MDPS unit, make sure to align the steering wheel to the center position.


 Locate the steering column guide bracket (A) and remove four (4) Torx[®] head screws (B/C) securing it to the steering column.

> Tightening torque: B: 3.6 lb-ft (4.9 Nm) C: 2.2 lb-ft (2.9 Nm)






 Lift the steering column guide bracket (D) and remove the plastic spacer (E). Retain all parts as they will be reused.




MDPS FLEXIBLE COUPLING REPLACEMENT

4. Remove the steering column guide bracket hinge bolt (F)

Tightening torque: 13~14.5lb-ft (17.7~19.6 Nm)




5. Remove the steering column guide bracket (G) from the steering column.



 Hold the MDPS upright and loosen four Torx[®] head screws (H) securing the column to the motor housing.

> Tightening torque: 6.5~9.4lb-ft (8.8~12.7 Nm)




Page 4 of 16

SUBJECT:

MDPS FLEXIBLE COUPLING REPLACEMENT


7. Separate the upper half (I) of the motor housing from the lower half (J).



8. Remove the washer-gasket (K) and connector (L) from lower portion of the MDPS.




To avoid damage, use caution when removing the connector.



9. Remove the 3 Torx[®] head screws (M) securing the MDPS ECU cover.

Tightening torque: 3.6~5.1lb-ft (4.9~6.9Nm)



Page 5 of 16

SUBJECT:

MDPS FLEXIBLE COUPLING REPLACEMENT

10. Remove the 4 Torx[®] head screws (N) securing the MDPS motor cover.


Tightening torque: 3.6~5.1lb-ft (4.9~6.9Nm)


11. Remove the MDPS motor cover.



To avoid damage, use caution when removing the connector and the wiring harness.

 Remove the original flexible coupling (O) from the housing. In addition, use an air gun to remove any foreign matter from the motor and/or the housing.







Page 6 of 16

SUBJECT:


MDPS FLEXIBLE COUPLING REPLACEMENT

13. Install the new improved flexible coupling onto the steering column.

***** NOTICE

Before installing the new part, make sure it has "HNBR" embossed on the surface.

The position of the flexible coupling is not specific and can be installed facing upward or downward.





14. Reinstall all removed components by reversing the order of removal. Perform the **Calibration Procedure found on page 13.**

* NOTICE


Before re-installing the MDPS unit, make sure the front wheels are pointing straight ahead.

MDPS FLEXIBLE COUPLING REPLACEMENT

Replacement Procedure 2: This procedure applies to Soul (AM), and Forte (YD) models.

NOTE: Images shown are for general information and not representative of each model's actual configuration.

 Remove the crash pad lower panel (A) by referring to "Body (Interior and Exterior) → Interior → Crash Pad → Repair procedures" on KGIS.




 Loosen three (3) steering column shroud retaining screws (B) and then remove the steering column upper and lower shrouds.

***** NOTICE

When loosening the steering wheel column shroud fixing screws, turn the steering wheel 90° to the left/right from aligned position.

3. Disconnect the MDPS electrical connectors (C).





Page 8 of 16

SUBJECT:


MDPS FLEXIBLE COUPLING REPLACEMENT

4. Disconnect the multifunction switch, wiper and washer switch, airbag, and heated steering wheel electrical connectors.

 Loosen both steering column retaining bolts (D) and rear bolt (E) and lower the steering column assembly.

> Tightening torque: 9.4~13.0 lb-ft (12.7~17.7 Nm)







MDPS FLEXIBLE COUPLING REPLACEMENT

6. Loosen the three MDPS motor retaining bolts (F) and lift the MDPS motor and set it to the side.

Tightening torque: 5.8~8.7 lb-ft (7.8~11.8 N-m)



 Remove the original flexible coupling (G) from the motor. In addition, use an air gun to remove any foreign matter from the motor and/or the housing.



Page 10 of 16

SUBJECT:

MDPS FLEXIBLE COUPLING REPLACEMENT


8. Install the new improved flexible coupling onto the steering column.

***** NOTICE

Before installing the new part, make sure it has "HNBR" embossed on the surface.

The position of the flexible coupling is not specific and can be installed facing upward or downward.

9. Reinstall all removed components by reversing the order of removal.





MDPS FLEXIBLE COUPLING REPLACEMENT


Replacement Procedure 3: This procedure applies to Cadenza (VG) models.

NOTE: Images shown are for general information and not representative of each model's actual configuration.


* NOTICE

Before removing the MDPS unit, make sure to align the steering wheel to the center position.

- 1. Remove the MPDS unit by referring to the applicable procedure on KGIS.
- 2. Remove 3 bolts (A) securing the MPDS motor to the housing.



3. Separate the MDPS motor (B) from the housing (C), as shown.




Page 12 of 16

SUBJECT:

MDPS FLEXIBLE COUPLING REPLACEMENT

 Remove the original flexible coupling (D) from the motor. In addition, use an air gun to remove any foreign matter from the motor and/or the housing.




5. Install the new improved flexible coupling onto the steering column.

***** NOTICE

Before installing the new part, make sure it has "HNBR" embossed on the surface.

The position of the flexible coupling is not specific and can be installed facing upward or downward.






***** NOTICE

Before re-installing the MDPS unit, make sure the steering wheel is aligned to the center position, with the front wheels pointing straight ahead.

6. Reinstall all removed components by reversing the order of removal. Perform **Calibration Procedure**.

Calibration Procedure used after procedure 1 and 3 ONLY:

- 1. Connect the power supply cable to the GDS.
- 2. Connect the USB cable between the VCI and the GDS.
- 3. Connect the Main 16-pin DLC cable (GHDM 241000) to the VCI.
- Connect the Main 16-pin DLC cable (GHDM – 241000) to the OBD-II connector, located under the driver's side of the instrument panel.



5. Select **EPS** and click on **OK**.

OPT	MA(TF/QF)	2014	G 2.0 T-GDI
System	EPS.		
	Select System	Select All	Selected System Clea
ENGINE AT THMS BSD CODE			🧭 Motor Driven Power Steering
(Group		Symptom


Page 14 of 16

SUBJECT:

7.

MDPS FLEXIBLE COUPLING REPLACEMENT

6. Select **Option Treatment** under the Vehicle S/W Management tab.



	💽 VCI : V	VLAN On 💿 VMI : Off	💽 Internet : On		-×
GD	Preparation	Diagnosis	Vehicle S/W Managemen	Repair	0
Vehicle > OPTIMA(TF	QF)/2014/G 2.0 T-GDI	System	Steering/Motor Dr	ven Power Steering	0 🖴
Vehicle S/W Management	Vehicle S/W Management				
ECU Upgrade	ID Register				
Audio Update	System Identifi	ication			
ID Register	- ojotom raonan	oution			
Option Treatment 🛛 🗈	Data Treatment				
This item is not supporte					
	ASP Calibration	n			
	Seps Type Reco	gnition			
<					
Data Treatment					
Inspection / Test					
ECU Mapping Verification X					
Selup FeedBack Ma	nual TSB DTC	Current Data Actuation Test	Flight Record Oscilloscope	Fault Code Searching ECU Upgrade	Internet Update
🗿 🩋 🚞 I	🔰 📴 🍕 📴	s 🕌 🎾	16 N P 2 4 4 L	a n 17 é i 1 d	() 7:51 AM 5/7/2014

GD Preparation Repair 0 **I** ECU Upg Audio Up ASP Calibration I ID Regis This function is used for initiating ASP Calibration. Perform this replace EPS ECU or do wor k related to EPS ready, press (OK) button Data Treat Cancel Inspection CurrentData Actuation Test Flight Record Oscilloscope Fault Code Searching ECU Upgrade TSB DIC . 828657**4**94488868840

Select ASP Calibration.

8. Click **OK** to continue with ASP calibration.

10.

and click OK.

MDPS FLEXIBLE COUPLING REPLACEMENT

9. Start the engine and center the steering wheel. Then, click **OK**.

Turn the ignition OFF and wait 15

seconds. Then, turn the ignition ON

 VCI: VXLAL Ca: VALI. Off @ Internet: Cn:

 Preparation

 Diagnosis

 Vehicle SW Management

 Repair

 OPTIMATE/CPP204/G 20 T-GOI

 Optimize

 Steering Motor Driven Power Steering

 Optimize

 Steering Motor Driven Power Steering

 Optimize

 ID Register

 Optimize

 Data Treatr

 Inservice

 EXU More Vehicles

 Management

 Register

 Optimize

 Data Treatr

 Inservice

 EXU Monge Veficiation

 Statistics

 The Motor

 Test

 Inservice

 Optimize

 Data Treatr

 EXU Monge Veficiation

 Statistics

 Freditions

 Manage 153

 OC

 Currentition

 Color

 Color

 Color

 Color

 Color

 Color

 Color

 Color

 Color

 Color
</

	()vci	: WLAN On 🛭 VMI :	Off 💿 Internet :	On				×
GD	Preparation	Diagnosis	Vehicle S/W N	lanagement	Re	epair	0	
Vehicle OPTIMA	TF/QF)/2014/G 2.0 T-GDI		Steerin	ng/Motor Driv	en Power S	teering	02	
Vehicle S/WM CASP Cal	ibration					0	10	Ð
ECU Upgr								
Audio Upd		[ASP Calibration]						
ID Registe								
Option Treatr		The second properties of the	for initiating ASP Calibr		related to EPS			
This item is		1939.0		or do work	related to EPS.			
		Initiatizing comp et utning the inpution kay to tor 15 sec Turn neat i,piniton kay to and Press (MK Check the steering a is within ±5° at data b	the Off position, wait he on position button, ngle sensor analysis.					
Data Treatr Inspection / ECU Mapping Verification II			Canc	9			J	
Setup	Manual TSB DTC	Current Data Actu	ation st Flight Record	Oscilloscope	Fault Code Searching	CU Upgrade	Internet Update	>
	D 605 🔍	GDS	2 K 5 P 2	614 L 1	N 15 4		10 754 AM	r.

- 11. Access **Current Data** and verify the Steering Angle Sensor value is at 0.0 \pm 5.0 degrees.

MDPS FLEXIBLE COUPLING REPLACEMENT

AFFECTED VEHICLE PRODUCTION RANGE:

Model	Applicable Production Range
Forte (TD) 2012~2013	Jan. 05, 2012 ~ Mar.31, 2013
Forte (YD) 2014	Jan. 7, 2013 ~ Dec.18, 2013
Soul (AM) 2010~2013	Sep. 01, 2009 ~ Aug. 15, 2013
Cadenza (VG) 2014	Feb. 01, 2013 ~ Apr.19, 2014

PART INFORMATION:

Part Name	Part No.	Qty.	Replacement Part
Flexible Coupling	56315 2K000FFF	1	

WARRANTY INFORMATION:

N CODE = N29 C CODE = C63

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	QTY.
Soul (AM)		56310 2K625		(CHA 074) MDPS Flexible	56315F00	1.0 M/H	56315 2K000FFF	1
Forte (TD)	W	56310 1M550	0		56315F02	1.6 M/H		
Cadenza (VG)	W .	56310 3R561	U	Coupling Replace		1.5 M/H		
Forte (YD)		56310 A7410				0.8 M/H		

***** NOTICE

The repair procedure to replace the flexible coupling of the MDPS Soul (AM) and Forte (YD) has been modified from the original repair procedure outlined in KGIS and previously in TSB CHA 044 (removal of certain parts as currently shown in the service procedure on KGIS is not necessary to complete the replacement of the flexible coupling). As a result, the labor time for the repairs for these models (includes inspection) have been adjusted.