



Michael A. Berardi
 Director
 Service Engineering Operations
 Ford Customer Service Division

Ford Motor Company
 P. O. Box 1904
 Dearborn, Michigan 48121

January 23, 2017

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**
Update Prior to Sale 16U32 – Supplement #1
 Certain 2017 Model Year F-250 to F-750 F-Super Duty Vehicles Equipped with a
 6.7L Diesel Engine
 Engine Oil Pressure Inspection

REF: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**
Update Prior to Sale 16U32
 Dated December 30, 2016

New! REASON FOR THIS SUPPLEMENT

Service Action Update: Service parts and repair instructions are now available to repair vehicles that fail the engine oil pressure inspection.

Labor Allowances: Claims with labor operation code 16U32B with a repair date of January 28, 2017 and later will no longer be accepted.

PROGRAM TERMS

This program will be in effect through December 31, 2017, for new unsold vehicles only, and is not applicable to sold vehicles.

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
F-250 – F-550	2017	Kentucky	February 3, 2016 through November 30, 2016
F-350 – F-550		Ohio	May 4, 2016 through December 6, 2016
F-650 – F-750			April 18, 2016 through December 6, 2016

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS PROGRAM

In some of the affected vehicles, the engine may lack oil pressure at start up after a cold soak due to concerns with the oil pump. This condition may lead to engine failure at very low mileage.

New! SERVICE ACTION

Before demonstrating or delivering any new in-stock vehicles involved in this program, dealers are to inspect for a lack of engine oil pressure and if necessary replace the engine front cover following the technical instructions found in Attachment III.

NOTE: *Less than 1% of the affected vehicles are expected to require engine front cover replacement based on the inspection.*

New! SERVICE ACTION (Continued)

NOTE: To ensure a positive customer delivery experience, dealers are requested to immediately conduct this procedure on all affected new in-stock vehicles in your inventory. The inspection procedure is a two-phase operation with an 8 hour wait between phases. Please ensure that adequate time is allotted to perform this procedure prior to the demonstration or delivery of vehicles affected.

OWNER NOTIFICATION MAILING SCHEDULE

Owner letters will not be mailed for this program.

New! ATTACHMENTS

Attachment I: Administrative Information

Attachment II: Labor Allowances

Attachment III: Technical Information

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,



Michael A. Berardi

NEW VEHICLE DEMONSTRATION / DELIVERY HOLD

Update Prior to Sale 16U32 – Supplement #1

Certain 2017 Model Year F-250 to F-750 F-Super Duty Vehicles Equipped with a 6.7L Diesel Engine
Engine Oil Pressure Inspection

OASIS ACTIVATION

OASIS will be activated on December 30, 2016.

FSA VIN LISTS ACTIVATION

FSA VIN Lists will be available through <https://web.fsavinlists.dealerconnection.com> on December 30, 2016.

SOLD VEHICLES

Repair affected vehicles brought to your dealership that exhibit low oil pressure under the applicable Ford Bumper-to-Bumper warranty coverage period.

STOCK VEHICLES

Correct all affected units in your new vehicle inventory before delivery.

TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this service action.

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For vehicles within new vehicle bumper-to-bumper warranty coverage, follow existing warranty and policy guidelines for related damage claims. No SSSC approval is required for these vehicles:
 - Ford vehicles – 3 years or 36,000 miles
 - F-650 / F-750 trucks – 2 years, regardless of miles driven

OWNER REFUNDS

Refunds are not approved for this program.

RENTAL VEHICLES

The use of rental vehicles is not approved for this program.

NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**Update Prior to Sale 16U32 – Supplement #1**

Certain 2017 Model Year F-250 to F-750 F-Super Duty Vehicles Equipped with a 6.7L Diesel Engine
Engine Oil Pressure Inspection

New! CLAIMS PREPARATION AND SUBMISSION

NOTE: Prepare and enter claims using Direct Warranty Entry (DWE) or One Warranty Solution (OWS).

- **DWE:** If you enter claims in the ACESII **Warranty** screen, enter claims using DWE.
 - Refer to ACESII Manual for claims preparation and submission information.
 - Use code information shown below:
 - Program Code (DWE) – 16U32
 - *Labor Operation – 16U32A or 16U32C (inspection dependent)*
 - Causal Component – 6019
 - Condition Code – 42
 - Customer Concern Code – E69
- **OWS:** Enter claims in Dealer Management Software (DMS). These instructions are only for dealers that have completed the launch to OWS and, as a result, are no longer able to reach ACESII online.
 - Refer to the OWS Manual for claims preparation and submission information.
 - Use code information shown below:
 - Claim Type 31 – Field Service Action
 - Sub Code (OWS) – 16U32
 - *Labor Operation – 16U32A or 16U32C (inspection dependent)*
- Additional labor and/or parts must be claimed as related damage on a separate repair line from the FSA.
- PROGRAM TERMS: This program will be in effect through December 31, 2017, for new unsold vehicles only, and is not applicable to sold vehicles.
- **Provision for Locally Obtained Supplies:** An allowance is provided for locally obtaining 2 gallons of diesel fuel.
 - Program Code: 16U32
 - Misc. Expense: OTHER
 - Misc. Expense: Claim actual cost up to \$8
- ***Provision for Metal Surface Prep Wipes:*** *One container of Metal Surface Prep Wipes (ZC-31-B) can be used on approximately 25 vehicles (one wipe per vehicle required). This provision is for the amount used for one vehicle repair. Submit on the same line as the repair.*
 - *Program Code: 16U32*
 - *Misc. Expense: OTHER*
 - *Misc. Expense: Claim up to \$10.00*

NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**Update Prior to Sale 16U32 – Supplement #1**

Certain 2017 Model Year F-250 to F-750 F-Super Duty Vehicles Equipped with a 6.7L Diesel Engine
Engine Oil Pressure Inspection

New! LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Engine Oil Pressure – PASS (no service required) This labor operation <u>closes</u> the program	16U32A	0.4 Hours
<i>Engine Front Cover Replacement – FAIL Includes Engine Oil Pressure Inspection</i>	<i>16U32C</i>	<i>16.7 Hours</i>

New! PARTS REQUIREMENTS / ORDERING INFORMATION

NOTE: Less than 1% of the affected vehicles are expected to require engine front cover replacement based on the inspection.

SSSC Web Contact Site:

To place an order for the engine front cover, submit a VIN-specific Part Order contact via the SSSC Web Contact Site.

Part Number	Description	Order Quantity	Claim Quantity
HC3Z-6019-A	Engine Front Cover	1	1

The DOR/COR number for this program is 51069.

Dealers will be notified via a DOES II communication if circumstances warrant a change in part supply strategy and when open ordering resumes.

Order the parts below through normal order processing channels:

Part Number	Description	Order Quantity	Claim Quantity
HC3Z-8527-B	Transmission Oil Cooler Coolant Tube O-rings (1/package, 2 needed)	2	2
BC3Z-6379-B	Crankshaft Pulley Bolts (4/package, 4 needed)	1	4
BC3Z-6700-A	Front Crankshaft Seal	1	1
BC3Z-6310-A	Front Crankshaft Slinger	1	1
W715618-S437	Torque Converter Nut (4/package, 6 needed)	2	6
N808684-S101	Steering Column Shaft Bolt	1	1
HC3Z-2A572-A	Vacuum Pump Gasket	1	1
W715106-S439	Engine Mount Cross Through Bolt (4/package, 2 needed)	1	2
W718444-S439	Engine Mount Bracket Bolt (4/package, 8 needed)	2	8

NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**Update Prior to Sale 16U32 – Supplement #1**

Certain 2017 Model Year F-250 to F-750 F-Super Duty Vehicles Equipped with a 6.7L Diesel Engine
Engine Oil Pressure Inspection

New! PARTS REQUIREMENTS / ORDERING INFORMATION (Continued)

Order the parts below through normal order processing channels (Continued):

Part Number	Description	Order Quantity	Claim Quantity
BC3Z-9439-C	Upper Intake Manifold Gasket (2/package, 2 needed)	1	2
BC3Z-9439-A	Upper Intake Manifold Gasket	1	1
BC3Z-9439-B	Upper Intake Manifold Gasket	1	1
W716088-S900	Turbo Coolant Outlet Tube Bolt (2/package, 1 needed)	1	1
BC3Z-6587-A	Turbo Mounting Gasket	1	1
W714639-S439	Turbo Mounting Bolt (1/package, 4 needed)	4	4
BC3Z-6N640-A	Exhaust Manifold to Turbo Inlet Pipe Gasket (2/package, 2 needed)	1	2
W711402-S900	Exhaust Manifold to Turbo Inlet Pipe Nut (1/package, 6 needed)	6	6
BC3Z-8287-A	Turbo Inlet Pipe to Turbo Clamp (1/package, 2 needed)	2	2
FC3Z-8287-A	Turbo Outlet Pipe to Turbo Clamp	1	1
W718005-S900	Turbo Outlet Pipe to Exhaust Bolt (2/package, 2 needed)	1	2
W520112-S442	Turbo Outlet Pipe Mount Nut (4/package, 2 needed)	1	2
W709771-S440	Transmission Mount Nut (1/package, 2 needed)	1	2
DC3Z-6710-A	Upper Oil Pan to Block Gasket (2/package, 2 needed)	1	2
DC3Z-6710-B	Upper Oil Pan to Block Gasket	1	1
DC3Z-6L621-A	Upper Oil Pan to Oil Cooler Gasket	1	1
DC3Z-6L621-C	Upper Oil Pan to Oil Cooler Gasket	1	1
DC3Z-6L621-B	Upper Oil Pan to Oil Cooler Gasket	1	1
BC3Z-6840-A	Upper Oil Pan to Oil Filter Adapter Gasket	1	1
DS7Z-19B596-A	A/C Line O-ring (1/package, 2 needed)	2	2
BC3Z-6731-B	Oil Filter	1	1
XO-10W30-QSD	SAE 10W-30 Super Duty Diesel Motor Oil	13 quarts	13 quarts
VC-3-B	Orange Concentrated Antifreeze/Coolant	1	1
XT-10-QLVC	Mercon LV Automatic Transmission Fluid	3 quarts	3 quarts
TA-357	High Performance Engine RTV Silicone	1	1

NEW VEHICLE DEMONSTRATION / DELIVERY HOLD**Update Prior to Sale 16U32 – Supplement #1**

Certain 2017 Model Year F-250 to F-750 F-Super Duty Vehicles Equipped with a 6.7L Diesel Engine
Engine Oil Pressure Inspection

New! PARTS REQUIREMENTS / ORDERING INFORMATION (Continued)

Order the parts below through normal order processing channels (Continued):

Part Number	Description	Order Quantity	Claim Quantity
ZC-30-A	Silicone Gasket Remover	1	1
PM-4-A	Metal Brake Parts Cleaner	1	1
XL-5-A	Multi-Purpose Grease Spray	1	1
TA-25-B	Threadlock Sealer (To be used for body bolts)	1	1
ZC-31-B	Metal Surface Prep Wipes (25/package, 1 needed)	1	Claim as Misc. OTHER

To guarantee the shortest delivery time, an emergency order for parts must be placed.

DEALER PRICE

For latest prices, refer to DOES II.

PARTS RETENTION AND RETURN

Follow the provisions of the Warranty and Policy Manual, Section 1 - WARRANTY PARTS RETENTION AND RETURN POLICIES.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

ERROR: undefined
OFFENDING COMMAND: eexec

STACK:

/quit
-dictionary-
-mark-