August 21, 2015

HONDA

Product Update: Electronic Power Steering (EPS) Software Update

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2013	Accord	ALL	Check the iN VIN status for eligibility
2014	Accord Plug-In	ALL	Check the iN VIN status for eligibility

BACKGROUND

When a failure is detected, the EPS control unit goes into back-up mode. The new software provides partial assist during back-up mode.

CUSTOMER NOTIFICATION

Owners of affected vehicles will be sent a notification of this campaign.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Some vehicles affected by this campaign may be in your new or used inventory. Repair these vehicles before they are sold.

CORRECTIVE ACTION

Use the HDS and the Mongoose Pro Honda Interface Tool to update the EPS software.

TOOL INFORMATION

Tool Name	Tool Number	Quantity
Mongoose Pro Honda Interface Tool	MGPHONDA	1

NOTE: This tool was automatically shipped to your dealership on June 12, 2015.

SOFTWARE INFORMATION

NOTE: Unnecessary or incorrect repairs resulting from a failure to update the HDS are not covered under warranty.

HDS Software Version: 3.016.042 or later.

3.010.042 01 later.

J2534 EPS Update: 5.01

J2534 Mongoose Drivers: 1.2.0.000

NOTE: If the EPS Rewrite icon is present on your laptop, your software is updated.



Page 1 of 6

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

Year/Model	Program ID	Program Part number	CM Part Number
2013 Accord 4-Door LX L4	39990-T2F-A020	39990-T2F-3050	39980-T2F-A014
2013 Accord Sport	39990-T2F-A810	39990-T2F-3070	39980-T2F-A814
2013 Accord 4-Door EX, EX-L, L4	39990-T2F-A920	39990-T2F-3060	39980-T2F-A914
2013 Accord 4-Door EX, EX-L, Touring, V6	39990-T2G-A910	39990-T2G-3050	39980-T2G-A914
2013 Accord 2-Door EX-L, L4	39990-T3L-A010	39990-T3L-3050	39980-T3L-A014
2013 Accord 2-Door EX-L, V6	39990-T3M-A910	39990-T3M-3050	39980-T3M-A914
2014 Accord Plug-In	39990-T3V-A030	39990-T3V-3050	39980-T3V-A013

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Template ID	Failed Part Number
5135A7	Update the EPS control unit software.	0.3 hr	15-055A	39980-T2F-A91

Defect Code: 5ZS00 Symptom Code: JT500

Skill Level: Repair Technician

BEFORE GETTING STARTED

NOTE:

- If unfamiliar with the Mongoose Pro Honda Interface tool or the Electronic Power Steering Rewrite Application, refer to the following Special Tools guides:
 - Mongoose Pro Honda User Guide (ST 01937)
 - Mongoose Pro Honda Quick Start Guide (ST 01934)
 - Accord EPS Rewrite Reference Guide (ST 01936)
- Connect a fully charged jumper battery to the vehicle and leave it connected during the entire procedure to maintain steady voltage.
- Never turn the ignition to OFF or ACCESSORY. If there is a problem with the update, leave the ignition turned to ON.
- To prevent EPS control unit damage, do not operate anything electrical (headlights, audio system, brakes, A/C, power windows, door locks, etc.) during the update.

DIAGNOSIS

Connect the HDS and check for DTCs in the EPS system.

- If DTC 53-01 torque sensor (low/high check) or DTC 53-02 torque sensor (average check) is stored, complete this bulletin and refer to SB 15-056, *Warranty Extension: EPS Torque Sensor (DTC 53-01 or DTC 53-02)* to replace the steering gear box.
- If DTC 53-01 or DTC 53-02 is not stored, go to REPAIR PROCEDURE.

REPAIR PROCEDURE

Updating the EPS with the Mongoose Pro Honda Interface Tool.

NOTE:

- Make sure you have the latest software loaded to your PC.
- During the software update, DO NOT turn off the ignition to OFF. Doing so during the update will damage the control unit.
- 1. Connect a jumper battery to the vehicle and leave it connected during the entire procedure to maintain a steady voltage.
- 2. Connect the Mongoose Pro Honda cable between the PC and the vehicle's DLC.
- 3. Select the EPS Rewrite Icon on your PC.




4. Click on the I Agree button.

"Honda") policies and term	s of use for Honda's reprogramming e to all terms and conditions stated	, Inc.'s (hereafter also referred to as g software. By using this software I herein. If you do not agree to these
OR IN LAW, INCLUDING T FOR A PARTICULAR PUR	HE IMPLIED WARRANTIES OF M POSE. IN NO EVENT WILL AMER	S, EXPRESS OR IMPLIED, IN FACT ERCHANTABILITY AND FITNESS RICAN HONDA BE LIABLE FOR DR DAMAGES, INCLUDING LOST

5. Click the Next button in the Pass-thru Device Selection screen.

Pass-thru Device Selection
Please select the Pass-Thru Device that you want to use.
Drew Technologies, Inc. MongoosePro Honda
 Cancel

6. Click on the Start button.



7. Click on the **Connect** button.

NOTE: Although the MVCI is shown in the screen captures, the Mongoose Pro Honda Interface Tool is actually used.

	Connect to Vehicle
1.	Connect the PC to the pass-thru device.
2.	Before reprogramming, test the vehicle battery and proceed if the result is good. Ensure the vehicle is connected to a battery booster while reprogramming the control module.
3.	At the vehicle, turn the ignition switch ON(II), then connect the pass-thru device to the vehicle's SAE J1962 connector (DLC).
4.	Click Connect to continue.

8. You will see the **Communication with the Vehicle** screen.

Communication with the Vehicle
Please wait until the acquisition of vehicle information is completed.
Help

9. Wait for the **EPS Update Information** screen to appear. Select **Yes**. The update will start and the screen will show a loading bar.

0	ant Des annus ID	Latest Deserves ID
	ent Program ID	Latest Program ID 39990-T2G-A910
399	90-T2G-A900	39990-12G-A910
	Latest Program	n information
System	EPS	
^o rogram ID	39990-T2G-A910	
Program Part No.	39990-T2G-3050-M1	
CM Part No.	39980-T2G-A914	
/ehicle Model	Accord	
Update Description	4Dr_17_V6	
se wait until the prog	ress bar reaches 100%.	
	iress bar reaches 100%. ous Program ID	Updating Program ID
Previo		Updating Program ID 39990-T2G-A910

10. Turn the ignition to OFF, then to ON within 60 seconds to complete the updating procedure.

	Reset the EPS Control Module	
	Turn the ignition switch OFF then ON within 60 seconds.	
Help		

11. The **EPS Update Successful** screen appears. Select **Complete**, then disconnect the Mongoose Pro Honda Interface Tool.

	Updated Program information	
System	EPS	
Previous Program ID	39990-T2G-A900	
Updated Program ID	39990-T2G-A910	
Program Part No.	39990-T2G-3050-M1	
CM Part No.	39980-T2G-A914	
Vehicle Model	Accord	
Update Description	4Dr_17_V6	
puale Description	401_17_90	

END