

TECHNICAL BULLETIN

Q524NAS1

28 JAN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 418-02

Service Action: Engine Bay Harness Anti-Abrasion Feature Missing

AFFECTED VEHICLE RANGE:

Discovery Sport (LC)
Model Year: 2016
VIN: 548350-550532
Assembly Plant: Halewood

MARKETS:

NAS

CONDITION SUMMARY:

Situation: An issue has been identified on a limited number of vehicles listed within the Affected Vehicle Range where polyvinyl chloride (PVC) tape instead of anti-abrasion tape has been used on an engine bay harness.

Action: Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

 **NOTE: when ordering parts, order only the expected percentage demand of parts identified.**

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
Tape	LR083490	1	100
Edge clip	YQR500220	1	100

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required tools.

WARRANTY:

 **NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**