631244



## Service Bulletin

File In Section:

08 - Body and Accessories

Bulletin No.:

02-08-42-001B

Date:

October, 2004















## **INFORMATION**

Subject: Chemical Damage To Exterior Polycarbonate Headlamp Lenses

Models: 2005 and Prior Passenger Cars and Trucks

2003-2005 HUMMER H2

This bulletin is being revised to add the 2004 and 2005 model years. Please discard Corporate Bulletin Number 02-08-42-001A (Section 08 — Body and Accessories).

The bulletin is being issued to make dealers and customers aware of chemical damage that may be caused to exterior polycarbonate headlamp lenses. Most late model vehicles have these types of headlamp lenses. This material is used because of its temperature and high impact resistance.

A variety of chemicals can cause crazing or cracking of the headlamp lens. Headlamp lenses are very sensitive. Care should be exercised to avoid contact with all exterior headlamp lenses when treating a vehicle with any type of chemical, such as those recommended for rail dust removal. Rubbing compound, grease tar and oil removers, tire cleaners, cleaner waxes and even car wash soaps in too high a concentration may also attribute to this condition. This could result in the need to replace the entire headlamp housing.

Also, crazing or deformations of the lens may occur if a shop mat or fender cover is draped over the fender and covers a portion or all of the headlamp assembly while the DRL or headlamps are on. This action restricts the amount of heat dissipated by the headlamps.

Once a heat buildup is generated by the headlamp, a degradation of the headlamp lens begins. This degradation of the lens can be unnoticeable at first and eventually manifest as spider cracks. In more extreme cases, it will begin to melt the lens of the headlamp.