TRIUMPH

Technical Bulletin 213
03.2021

Contents		
Item	**Subject**	**Model Affected**
213.1	Scrolling Indicators - Instrument Software Update	Rocket 3 GT, Rocket 3 R, Rocket 3 TFC, Rocket 3 GT Triple Black, Rocket 3 R Black

Item:	213.1
Description:	**Scrolling Indicators - Instrument Software Update**
Model Affected:	**Rocket 3 GT, Rocket 3 R, Rocket 3 TFC, Rocket 3 GT Triple Black, Rocket 3 R Black**

It has come to our attention on the above models that the instrument software needs updating before accessory scrolling indicators are fitted. The revised instrument software is available on Triumph diagnostic tool version 2021-04.

⚠ **Caution**
If accessory scrolling indicators are fitted before this software update there is risk that there will be permanent damage to the indicators.

Before fitting accessory scrolling indicators to the above models, dealers are requested to make sure that the latest instrument calibration is downloaded. After updating the instruments, connect to the Instrument Diagnostics Build Data Screen and make sure the application software part number and issue level are reported as:

- Application Software Part Number – 02570023
- Application Software Issue Level – 030000

When ordering replacement parts, refer to the EPC.

Circulation

Initial and date when read and return to central file holder

Service Manager	Parts Manager	Sales Manager	Workshop Supervisor	Technician 1	Technician 2