

Special Service Message



NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 60137 - SDD enhancements for fuel gauge and pump issues - 10MY onwards

Models : LA - Discovery 4 / LR4

LF - Freelander 2 / FL2

LM - New Range Rover

LS - Range Rover Sport

Engineer Name : Hawkeswood Paul

Last Modified : 19-10-2012 07:06:42

Category : Engine

Symptom : 404000 Fuel System Concerns

Content : **Issue :** Fuel gauge and fuel pump diagnosis using SDD

Cause: Various fuel pump and gauge issues / DTC

Action - This Special Service Message has been released to advise that improved diagnostic information and pin point tests have been released on SDD, for 10MY vehicles onwards.

It is not possible to list all of the improvements in this Special Service Message. Improved diagnostic areas include:

- Fuel level sensor tests
- Fuel gauge tests
- Fuel pump tests

The changes have been released over several SDD releases, beginning at DVD 127.

Please make sure the latest SDD DVD and patches are loaded to take advantage of this new diagnostic information.