

Audi ElsaWeb Newsletter

Edition 19: January 14, 2013

Content

- Elsa News and Updates
- Feedback Corner
- Technical Bulletins
- <u>Campaigns</u>
- <u>Updates</u>
- Repair Manuals
- Wiring Diagrams
- Suggestions



Elsa News and Updates

ElsaWeb users will soon see a new pop-up messaging feature when first logging in to ElsaWeb called "Elsa News and Updates." The feature's purpose is to display important communications, such as system outages, as well as provide links to different topics and archived messages. This feature also may be used for asking a survey question to help the Service Information Team gain valuable feedback.

The messaging feature will be fully controllable. You can jump to topics, view archived messages, and close the feature at any time. Additionally, the feature will timeout after several minutes of inactivity or will close after a set number of minutes. If the feature closes before you have the chance to read its contents, you can view the information on ServiceNet.

The new Elsa News and Updates messaging feature is another way that the Service Information Team is helping you keep informed of all things having to do with ElsaWeb.

Feedback Corner

This week's feedback is from Heinz, regarding a 2013 allroad Repair Manual. He stated:

"The complete engine mechanical section is missing in ElsaWeb for the 2.0 TFSI engine (CPMA engine code)"

This feedback was reviewed by the Service Information Team and the Repair Manual was fixed to show the correct data. We really appreciate you sending in feedback to help improve the quality of the Repair Information.

Feedback Status				
New	Completed	To Factory		
10	7	19		

^{*}Please note that this feedback feature is not the place to obtain technical assistance for Audi vehicles, or to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create an Audi Technical Assistance ticket and contact the Audi Technical Assistance at (800)-678-2389.

Back to top

Technical Bulletins

94 Moisture accumulation in headlamps (2028277/5)				
Model(s)	Year	Vehicle Specific Equipment		
Q7	2010-2014	Not Applicable		
Condition:				
 Considerable moisture present in headlamp. The moisture disappears only after extended drives (greater than 10 minutes). 				

Back to top

Campaigns

No new Campaigns in ElsaWeb.

Back to top

Updates

No new Updates in ElsaWeb.

Back to top

Repair Manuals

Repair Manuals					
Elsa Name	Model	Book Updated	Reason		
8F,8K,8T	A5 Cabriolet 2010> A4 2009> A5 2008>	Engine Mechanical CAEB,CPMA	Feedback# 685571		
4F	A6 2005–2011	Heating, Ventilation and Air Conditioning	Feedback# 683835		
8E,8H	A4 2002–2008 A4 Cabriolet 2007–	Fuel Injection and Ignition	Feedback# 718801		

	2009		
8F,8K,8T	A5 Cabriolet 2010> A4 2009> A5 2008>	Fuel Supply System	Feedback# 695668
Multiple	Multiple	Maintenance Intervals	Feedback# 691683

Back to top

Wiring Diagrams

No new Wiring Diagrams in ElsaWeb. Back to top

Suggestions:

Please send comments or suggestions to: aoa.WorkshopInformation@audi.com

Back to top

© 2012 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.