

Subject		Market
Vibration/Pulsation While Braking		USA
Service Category	Section	
Brake	Brake (front)	
Applicability		
2013-2017MY Tundra		

APPLICABLE VEHICLES

2013-2017

Tundra

CONDITION

Some 13-17MY Tundra vehicles may exhibit a vibration/pulsation during light to hard braking. The vibration/pulsation feeling can be described as being felt in any combination of the following: Steering wheel, brake pedal, seat, and entire vehicle. This condition is felt over a large range of speed, unlike drive shaft and wheel balance concerns.

RECOMMENDATIONS

- Please do not disassemble. Create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

LINK REFERENCES

This Tech Tip does not contain any link references