

[Next Unread Message](#)

View Message

Sent on	03	16	2016	Expires on	03	30	2016
From	Parts and Service Division						
Subject	Request for Parts: 2014-2016 RLX High Pressure Fuel Pump Noise						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2014-2016 RLX High Pressure Fuel Pump Noise

**This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda (AHM) is investigating certain 2014-2016 RLXs with a client complaint of a chirping noise coming from the high pressure fuel pump during engine operation. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to duplicate the issue.
2. Troubleshooting leads technician to replace high pressure fuel pump (16790-R9P-A01 or 16790-R9S-A01).

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.