

CAUTION: All involved customers must be notified, all involved units must be corrected as per instruction herein.

	Campaign no.: 2014–0003		
March 28th, 2014	Subject: A - Fast Flasher Blink Rate	No.	2014-2
	B - Possible Defective Ignition Key	REVISION 3	
	C - Front Storage Compartment Cover and/or Seat Will Not Open - Defective Ignition Switch	Noven	nber 6, 2014

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
2014	RS - ST - RT	ALL	See list

This bulletin has been superseded by: Warranty Campaign Bulletin 2014-8

(Campaign numbers on this bulletin are no longer active)

PROBLEMS

A - Fast Flasher Blink Rate

B - Possible Defective Ignition Key

C - Seat and/or Front Storage Compartment Cover Will Not Open - Possible Defective Ignition Switch

SOLUTIONS

A - Fast Flasher Blink Rate

B - Possible Defective Ignition Key

C - Seat and/or Front Storage Compartment Cover Will Not Open - Possible Defective Ignition Switch