| Reference | SSM72933 |
|---------------|--|
| Models | F-PACE / X761 |
| Title | Creak or Groan noise from lower steering column |
| Category | Chassis |
| Last modified | 14-Sep-2016 00:00:00 |
| Symptom | 303000 Steering/Handling |
| Content | Issue: A customer may report a creak / groan noise coming from the lower steering column area. |

Cause:

Currently under investigation - your support with further information about this concern will assist.

Action:

If this condition is present on the vehicle please raise an ePQR with a photo/video along with as much of the following as possible:

- Does the noise occur more when engine is hot or cold (under bonnet temperature) or no difference?
- Does the occupant cabin temperature have an effect (HEVAC unit setting?)
- · Is noise evident from vehicle start up, or does it take some time to occur?
- Does adjusting the steering column up or down have an effect?
- Does noise only occur at certain steering column rotation speed or amount of rotation - e.g slow speed/large angle or fast speed/small angle?
- Is noise affected by direction of steering wheel rotation worse in one direction (clockwise or anti-clockwise)?
- When lubricant has been applied to eliminate noise what was the lubricant and where was it applied?