



Service Bulletin

PRELIMINARY INFORMATION

Subject: Odometer Limited To 299999 Miles/KM

Models: 2003-2008 Pontiac Vibe

This PI was superseded to update Recommendation/Instructions. Please discard PIC4478B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer might comment that their odometer will NOT advance past 299,999 Thousand Miles/KM. This is a mechanical limitation of the odometer in the instrument cluster.

Recommendation/Instructions



The cluster CANNOT be reprogrammed to advance the mileage past this display limitation. If customer requests replacement or reprogramming of cluster to "0" KM at their expense, please refer to the latest version of PIT4720 for proper documentation of change.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION