



Tech Tips

TT 69-16-01

Date: September 23, 2016

DTC U0151, Active Lost Communication with Occupant Restraint Controller

If the Totally Integrated Power Module (TIPM) was recently replaced, make sure the transport fuse is fully inserted. See yellow fuse in Figures 1 and 2.

