

[Next Unread Message](#)

**View Message**

<b>Sent on</b>	02	19	2016	<b>Expires on</b>	03	03	2016
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Request for Parts: 2015 TLX Electronic Parking Brake (EPB) Actuator Inop						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers/Consultants  
From: Technical Research & Support Group  
RE: Request for Parts: 2015 TLX Electronic Parking Brake (EPB) Actuator Inop

Print this i/M message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2015 TLXs with a client reporting on ignition start, the Electronic Parking Brake (EPB) will not release causing one or both rear wheels not to move and/or "Check Parking Brake" warning message displays in MID. To fully understand the cause of this occurrence, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

- 1. One or more of these EPB related DTCs may be set: C1100, C1110, C1111 or C1120.
- 2. Troubleshooting leads technician to replace the EPB Actuator.
- 3. No previous repairs.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.