



Service Bulletin

PRELIMINARY INFORMATION

Subject: Illuminated MIL DTC P0747 Or P0796 May Be Set As An Active Or History Code In The TCM

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	ATS CT6, CTS, Escalade	2017	2017	All	All	All	8L45 (M5T) (M5N) and 8L90 (M5U) (M5X)
Chevrolet	Camaro, Corvette, Silverado, Suburban, Tahoe	2017	2017	All	All	All	8L45 (M5T) (M5N) and 8L90 (M5U) (M5X)
GMC	Sierra, Yukon	2017	2017	All	All	All	8L90 (M5U) (M5X)

Involved Region or Country	North America and N.A. Export Regions
Additional RPO/s:	N/A
Condition	Some customers may report an illuminated check engine light and the technician may find DTC P0747 and/or P0796 set in the TCM .
Cause	Engineering is currently investigating a solution for unwanted setting of DTC P0747 and P0796..

Service Procedure

DTC P0747 and/or P0796 should be cleared and the vehicle driven in an effort to duplicate DTCP0747 and/or P0796 resetting.

If the DTC's do not reset the vehicle should be returned to the customer.

If DTC P0747 and/or P0796 does reset on the test drive published Service Information diagnostics should be followed.

Version	2
Modified	09/30/2016 Updated Model Years

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools,

safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION