

Reference	SSM72188
Models	Discovery Sport / L550
Title	L550 Door Trim Removal Process
Category	Noise Vibration
Last modified	23-Feb-2015 00:00:00
Symptom	703000 Vibration Concerns
Attachments	L550 Plastic door pad protection.pdf
Content	<p><u>Issue:</u> An audible 'tis' is experienced from the door trim area when the audio is switched on.</p> <p><u>Cause:</u> The plastic tab, used to hold the protective casing on for transport, has broken and requires removal as this can cause vibration.</p> <p><u>Action:</u> Please ensure the plastic tab is removed in full from behind the door casing after removal of the protective casing. This is done by:</p> <ul style="list-style-type: none">• Pulling on the tab (Fig.1), the tab should break away from the door clip (Fig.2).• If the plastic tab breaks and the full tab has not been removed, please remove door casing and remove (Fig. 3).