

# Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

## SSM 72352 - L550 Headliner Modification for Fan Harness

**Models :** LC - Discovery Sport

**Engineer** Campbell Andy

**Name :**

**Last** 24-08-2015 09:12:17

**Modified :**

**Category :** Body

**Symptom :** 105000 Roof Options

**Content :** Issue

A number of L550 Discovery Sport headlining's have been supplied that may require modification to allow the fitment of the fan harness, by cutting out a square hole in the headlining.

### Cause


A modification to the part specification after release.

### Action


A small square section of the headlining will need to be cut out with a suitable tool (eg. knife) to allow the fan harness to pass through.

- Please see attachment Figure 1, for details and dimensions of the modification required.
- Note: the area will be covered by the body of the rear view mirror when complete - Please see attachment fig 2.

**File :** [headlining\\_mod.pdf](#)



**Fig 1**



**Fig 2**