

AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

December 2016

This notice applies to your vehicle: XXXXXXXXXXXXXXXXXXXX

RE: 2013–14 Accord Plug-In

Dear _____ :

What is the reason for this notice?

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. The Electric Power Steering (EPS) torque sensor may contain a manufacturing defect. If the EPS control unit detects a torque sensor failure, it is programmed to generate an error code and will disable the power-assist.

What should you do?

Please contact any authorized Honda dealer for an appointment to have your vehicle updated. The dealer update the EPS software. This work will be done *free of charge*.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this product update may cause you.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #15-055

JT5