

# **Engineering Request for Investigation**

BER15040A

## 2015 TLX Electronic Parking Brake (EPB) Actuator Inop.

### Background

American Honda (AHM) is investigating certain 2015 TLXs with a client reporting both rear wheels are locked up and/or the parking brake error message is displayed. To fully understand the cause of this occurrence, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

#### Qualifiers

- 1. Troubleshooting leads technician to replaced EPB Actuator.
- 2. No previous repairs.

### **Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.