View Message

Sent on	05	29	2015	Expires on 06	12	2015	
From	Parts and Service Division						
Subject	Request for Visit: 2013-15 Accord & Crosstour No Start or Intermittent Grinding						

Message PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors From: Technical Research & Support Group

Re: Request for Visit: 2013-2015 Accord & Crosstour No Start or Intermittent Grinding Noise

This message is solely directed to Honda dealership personnel; please handle accordingly. Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda (AHM) is investigating certain 2013-2015 Accords & Crosstours with the customer reporting a no start or grinding noise when trying to start. To fully understand the cause of this occurrence, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

- First time complaints only.
- 2. V6 engine with 6AT only.
- 3. Vehicle must be manufactured BEFORE 05/2014 (Refer to the FMVSS certification label on the B-Pillar).
- No previous repairs (must have original battery, starter, torque converter and no charging or starting system repairs).

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.