

[Next Unread Message](#)[View Message](#)

Sent on	03	22	2017	Expires on	04	05	2017
From	Parts and Service Division						
Subject	Request for Visit: 2016 MDX MIL On with DTC P0300-P0306 Stored (Zone 3)						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
 From: Technical Research & Support Group
 RE: Request for Visit: 2016 MDX MIL On with DTC P0300-P0306 Stored

**This message is solely directed to Acura dealership personnel; please handle accordingly.
 Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda (AHM) is investigating certain 2016 MDX with a client complaint of the Malfunction Indicator Lamp (MIL) On with the DTC P0300 (Random Misfire Detected), P0301 (No. 1 Cylinder Misfire Detected), P0302 (No. 2 Cylinder Misfire Detected), P0303 (No. 3 Cylinder Misfire Detected), P0304 (No. 4 Cylinder Misfire Detected), P0305 (No. 5 Cylinder Misfire Detected) and/or P0306 (No. 6 Cylinder Misfire Detected) stored. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

- One or more P0300 through P0306 DTCs must be stored.
 P0300 (Random Misfire Detected)
 P0301 (No. 1 Cylinder Misfire Detected)
 P0302 (No. 2 Cylinder Misfire Detected)
 P0303 (No. 3 Cylinder Misfire Detected)
 P0304 (No. 4 Cylinder Misfire Detected)
 P0305 (No. 5 Cylinder Misfire Detected)
 P0306 (No. 6 Cylinder Misfire Detected)
- No repair has been attempted for this issue.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.