

[Next Unread Message](#)**View Message**

Sent on 04 05 2015 **Expires on** 04 19 2015
From Parts and Service Division
Subject Request for Visit: 2015 TLX with Vibration at Highway Speeds (Zone 2)

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Visit: 2015 TLX Vibration at Highway Speeds

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2015 TLXs with clients reporting a vibration at highway speeds. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. V6 SH-AWD (18in. GOODYEAR) Only.
2. Vehicle has not been involved in any collision.
3. No accessory wheels/tires.
4. No previous repair for this issue.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.