

---

## **2016-2017 Fit & HR-V SRS Light On with Impact Sensor DTCs**

---

### **Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2016-2017 Fits & HR-Vs with a customer complaint of the SRS Light On with the impact sensor DTCs stored.. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

### **Qualifiers**

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. First time complaint only.
2. Any one of the following DTCs must be stored.
  - B0090-87 (No Signal from the Left Front Impact Sensor)
  - B0091-87 (No Signal from the Left Side Impact Sensor-First)
  - B0092-87 (No Signal from the Left Side Impact Sensor-Second)
  - B0095-87 (No Signal from the Right Front Impact Sensor)
  - B0096-87 (No Signal from the Right Side Impact Sensor-First)
  - B0097-87 (No Signal from the Right Side Impact Sensor-Second)
  - B280A-87 (No Signal from the Rear Safing Sensor) – HR-V Only

### **Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.