

[Next Unread Message](#)

**View Message**

**Sent on** 02 06 2015 **Expires on** 05 06 2015  
**From** Acura Parts, Service & Technical Division, Campaign Administration  
**Subject** Recall: 2002-03 CL & TL Airbag Inflator SERVICE BULLETIN UPDATE

DATE: February 6, 2015


TO: All Acura Service Managers and Personnel  
 FROM: Acura Parts, Service & Technical Division, Campaign Administration

RE: Recall: 2002-03 CL & TL Airbag Inflator **SERVICE BULLETIN UPDATE**

Today, February 6, 2015, Acura is announcing a modification to the procedure listed in service bulletin 10-026, *Safety Recall: Replacement Driver's Airbag Inflator May Be Over-Pressurized* to omit the inspection procedure for Takata airbags.

The original intent of service bulletin 10-026 safety recall was to identify a specific lot of suspect airbag inflators, and replace them with an improved part. The new direction for this recall population is to **replace the airbag inflator in all affected units** with a part that has been further improved and available since September 12, 2014.

Because the inspection is no longer a valid procedure for this campaign, vehicles that have previously been inspected as OK or have been repaired with a new inflator prior to September 12, 2014 will require further action. These VINs have already been added to service bulletin 14-029, *Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity* and will require new inflator to be installed. Vehicles repaired with a new inflator between September 12, 2014, and February 4, 2015, do not require further action at this time for driver's airbag inflator concerns. Please refer to the following diagram:



Acura urges all dealers to submit pending claims for service bulletin 10-026 within the next week. Doing so will facilitate proper handling of VINs that require further action.

[Click here for diagram image](#)

[▲ BACK TO TOP](#)