

Classification:

EL17-011

Reference:

ITB17-029

Date:

March 30, 2017

2017 QX30; PUSH-BUTTON IGNITION SWITCH MID-YEAR CHANGE

APPLIED VEHICLES: 2017 QX30 (H15)

SERVICE INFORMATION

A mid-year change has been made to the ignition system in the Applied Vehicles.

Vehicles produced November 3, 2016 and after (see VIN information on page 2) are equipped with a push-button ignition switch instead of a turning ignition switch.

See page 2 to view images of both ignition switches.

WARNING:

- Do NOT retrofit the push-button ignition switch to vehicles produced before the application date. Please reference Infiniti Parts and Service Bulletin IPSB/16-422.
- Modifications to the ignition switch are unauthorized, and may violate Federal law by making inoperative a device installed in compliance with Federal safety standards.
- Damage or failure due to changes or modifications to the ignition switch system are not covered under the terms of the warranty.
- Damage or failure due to changes or modifications to the ignition switch system are not subject to indemnification under the terms of the Infiniti Dealer Sales and Service Agreement.
- Retailers may be obligated under their Sales and Service Agreement to indemnify Infiniti for any damages, injuries, or deaths caused by modification of the ignition switch system.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

Vehicles built **BEFORE**
VIN: SJK(*)H5C(**)HA 029900




Figure 1

Vehicles built **AFTER**
VIN: SJK(*)H5C(**)HA 029899




Figure 2

