

**Tech Tip** T-TT-0330-15

April 07, 2015

## Clock Inoperative/Unable to Adjust Clock

Market **USA** 

Vehicle Interior

Applicability

Meter/Gauge/Display

2014-2015

2015

All Applicable Models

## **APPLICABLE VEHICLES**

2014-2015	Camry
2015	Sienna
2014-2015	Camry HV

Tundra Tacoma

CONDITION

Clock becomes inoperative, has dashes displayed, or cannot be adjusted

## **RECOMMENDATIONS**

If the GPS icon on the navigation screen\* shows a red slash through it and the clock shows dashes, verify the GPS antenna and antenna connection to the radio. If an antenna issue occurs and "Auto Adjust by GPS" is checked, the clock will be inoperative and cannot be adjusted.



If the GPS icon on the navigation screen\* is grey but has no slash through it and the clock shows dashes, move the vehicle outside to get a GPS signal.



\*If equipped.

## LINK REFERENCES

This Tech Tip does not contain any link references

Expires on

04/07/2016

© 2015, Toyota Motor Sales, USA

Page 1 of 1