Wireless Charging - Inaccurate Fully Charged Status for Motorola Droid Phones

Service Category

Vehicle Interior

Applicability

Avalon/HV & Camry/HV

Section

Power Outlets (int)

APPLICABLE VEHICLES

2015 2013-2015 Camry Avalon HV 2013-2015

2015

Avalon Camry HV

USA

CONDITION

Some customers may get an inaccurate fully charged indicator status from the wireless charging pad, even though the cell phone may not be fully charged.

This condition affects Motorola Droid Phones.

RECOMMENDATIONS

This condition is due to compatibility of mobile phones with wireless charging. Motorola Droid phones send a "charge complete" message to the wireless charger even though the phone may not be completely charged.

Please advise customers that they should not rely on the charging pad indicators to validate if the cell phone is fully charged as there may be a false reading if it's a Motorola Droid Phone.

Note: Because of the phone compatibility, replacing the wireless charger will not resolve the issue.

LINK REFERENCES

This Tech Tip does not contain any link references

Expires on

04/13/2016

© 2015, Toyota Motor Sales, USA

Page 1 of 1