



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Timeshift Function Inoperative

**Models:** 2010-2011 Buick Lacrosse  
2011 Buick Regal  
2010-2011 Cadillac SRX  
2010-2011 Chevrolet Equinox  
2011 Chevrolet Cruze  
2010-2011 GMC Terrain  
Equipped with RPO UYS Navigation Radio

*This PI was superseded to update recommendations. Please discard PIC5677.*

### Condition/Concern

Some customers may complain that the timeshift feature is inoperative (Timeshift is the ability to pause live radio).

### Recommendation/Instructions

If this concern is encountered, replace the radio with the latest part number listed in the parts catalog and reevaluate for concern.

**Important:** Equivalent refurbished radios may be received with a different part number.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
3420840	Radio Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION