



Service Bulletin

TECHNICAL

Subject: Stop/Start System Inhibited with Malfunction Indicator Lamp (MIL) Illuminated, DTC P16DC Set

Attention: This Bulletin also applies to any of the listed models equipped with Stop/Start System that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	ATS	2016	2016	SOP	G0175309	LTG, LGX	
	CTS						
Chevrolet	Malibu			SOP	GF247953	LFV	

Condition	<p>Some customers may comment on any of the following conditions:</p> <ul style="list-style-type: none"> • Stop/Start system is inoperative. • Message "Stop/Start System Disabled" appears on the DIC. • Malfunction Indicator Lamp (MIL) being illuminated. <p>A Technician may find DTC P16DC set.</p>
Cause	DTC P16DC disables the Stop/Start System.
Additional Options	Start/Stop System (RPO KL9)

Correction

A revised calibration has been developed to address these concerns. Update the Engine Control Module (ECM) using the Service Programming System (SPS).

Warranty Information

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	2
Modified	April 25, 2016 – Adding Cadillac to Model section.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION