



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Light With DTC U0111

Models: 2011-2013 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may experience a SES lamp with a current or history code U0111.

Recommendation/Instructions

If you experience this DTC, please don't replace the Battery Energy Control Module (BECM). Update the BECM with the latest calibrations in TIS-2-Web. A new calibration has been released to address this issue.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N9703	Reprogram Battery Energy Control Module	0.4

* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION