



Preliminary Information

PIP5445A Malfunction Indicator Lamp Illuminated With DTC P2097

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2016 - 2017	All	All	1.5L LFV	All

Involved Region or Country:	North America
Condition:	A technician may encounter a customer's vehicle with a Malfunction Indicator Lamp (MIL) illuminated, and a P2096 or P2097 set as a current or history DTC.
Cause:	Under Investigation at this time.

Correction:

Test for and repair any crankcase, induction or exhaust system air leaks.

Check the Rear HO2S circuit resistance, terminal tensions, crimps and locks.

If no related concerns are isolated, do not perform further diagnosis or replace related components at this time. (IE: HO2S / ECM / HARNESS)

Powertrain is aware of this concern and reviewing options.

Warranty Information

Operation	Description	Labor Time
4081378*	Powertrain Leak Testing and HO2S Harness Inspection	0.5 hr
* This is a unique labor operation for bulletin use only.		

Version History

Version	
2	
	2/2/2017 - Updated to correct verbiage.

