

GM CUSTOMER CARE AND AFTERSALES
DCS3000
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 10, 2013

Subject: 13186 – Service Update Bulletin
Incorrect Battery Current Sensor on Negative Battery Cable Assembly
Revised VIN List

Models: 2013 Cadillac Escalade, Escalade ESV; Chevrolet Tahoe, Suburban;
GMC Yukon, Yukon XL; 2013-14 Chevrolet Captiva, Captiva Sport;
2014 Chevrolet Silverado, GMC Sierra

To: All Cadillac, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors announced Service Update Bulletin 13186 on June 26, 2013. A VIN list of involved vehicles in dealer inventory was attached to the message. The list included 3/4 and 1 ton vehicles, in error. We are in the process of manually closing these in the "Investigate Vehicle History" (IVH) screen.

Attached to this message is a revised VIN list of involved vehicles in dealer inventory.

Please discard all copies of the previous involved VIN list that was sent to you and begin using the attached list to inspect and repair involved vehicles in dealer inventory.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES