



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Rear Toe Cam Adjustment Nut for Service Applications

**Models:** 2005 - 2015 Chevrolet Equinox  
2010 - 2015 GMC Terrain  
2006 - 2009 Pontiac Torrent  
2002 - 2009 Saturn VUE

*This PI was superseded to update Models and Years. Please discard PIT3117H.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Rear toe cam adjustment nut for service applications. The SI Documents for Rear Toe Adjustment refers to a cam nut available for service to adjust rear toe, but does not list any part numbers.

### Parts Information

Part Number	Description	Vehicle(s)
11519455	NUT,RR SUSP UPR CONT ARM (UPR CONTROL ARM INNER CAM)	2002 - 2004 SATURN VUE
11562237	NUT,RR SUSP UPR CONT ARM (UPR CONTROL ARM INNER CAM)	2005 - 2009 SATURN VUE
11570574	NUT,RR SUSP UPR CONT ARM (UPR CONTROL ARM INNER CAM)	2005 - 2015 EQUINOX 2006-2009 TORRENT 2010 -2015 TERRAIN

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION