



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp P16F3

Models: 2016 Chevrolet Colorado
2016 GMC Canyon
With Engine 2.5L RPO Code LCV

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

On rare occasions, a customer may have a vehicle concern of the check engine lamp being illuminated.

This may also be an intermittent concern.

Recommendation/Instructions

If the technician finds P16F3 with or without other codes in the ECM, check to see if updated calibrations are available for the ECM.

The description of the updated calibration(s) may not acknowledge that it repairs P16F3.

If updated ECM calibrations are available, install them and evaluate the vehicle to confirm the vehicle is repaired.

If updated calibrations are not available or trouble code P16F3 is not found in the ECM, follow normal diagnostics in Service Information.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION