

[Next Unread Message](#)**View Message**

Sent on 12 19 2014 **Expires on** 03 19 2015
From Acura Parts, Service & Technical Division, Campaign Administration
Subject Product Update: 2015 TLX Cross Traffic Monitoring Audible Alert

TO: All Acura Sales, Service & Parts Managers and Personnel
FROM: Acura Parts, Service & Technical Division, Campaign Administration

RE: Product Update: 2015 TLX Cross Traffic Monitoring Audible Alert Does Not Function

Today, December 19, 2014, Acura is notifying all dealers of a **Product Update** for 7,745 2015 TLX vehicles.

As approximately 3,000 TLX V6s are on STOP SALE, awaiting transmission inspections, there is an opportunity to address these vehicles now. We encourage dealers to update any new or used vehicles in dealer stock per S/B 14-054, *Product Update: Cross-Traffic Monitoring System – No Audible Alert* prior to sale in order to avoid future customer inconvenience.

Refer to iN VIN Inquiry status to determine which vehicles in your inventory are affected.

Problem

The Cross Traffic Monitoring system audible warning is disabled on TLX Tech models due to a software error.

Repair

Affected vehicles require a software update to enable the Cross Traffic Monitoring system audible warning function.

Parts

No parts are required. Updated software is currently available in MVCI control module update application version V3.01.40 or later, database update 12-Nov-2014 or later, and HDS software version 3.015.023 or later.

Warranty

Warranty information is detailed in S/B 14-054, *Product Update: Product Update: Cross-Traffic Monitoring System – No Audible Alert*.

Service Bulletin

In support of this product update, S/B 14-054 has been posted on ISIS as of December 19, 2014. It includes repair and warranty information related to this campaign.

Customer Notification

Acura expects to complete initial client notification by late January 2015.

As always, make sure to check the iN VIN status inquiry to determine if a vehicle is eligible for this product update.

Click [here](#) for a copy of service bulletin 14-054.

 [BACK TO TOP](#)

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.