

[Next Unread Message](#)**View Message**

---

**Sent on** 01 20 2015 **Expires on** 02 03 2015  
**From** Parts and Service Division  
**Subject** Request for Parts: 2014 Accord Hybrid MIL On with DTC P0134 Stored

**To:** All Honda Service Managers/Consultants  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2014 Accord Hybrid MIL On with DTC P0134 Stored

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2014 Accord Hybrid with a complaint of the Malfunction Indicator Lamp (MIL) on with P0134 (Air Fuel Ratio Sensor [Bank 1, Sensor 1] Heater System Malfunction) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to your attempting any repair.

**Qualifier**

AHM is interested ONLY if the vehicle meets the following requirement:

1. DTC P0134 must be stored.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.