

<b>Reference</b>	SSM73369
<b>Models</b>	Discovery Sport / L550 Range Rover Evoque / L538
<b>Title</b>	Exterior Rear View Mirror - Temperature sensor
<b>Category</b>	Body
<b>Last modified</b>	05-May-2017 00:00:00
<b>Symptom</b>	103000 Mirrors

**Content**      Issue: Exterior rear view mirrors are being replaced unnecessarily.

Cause: Inaccurate temperature readings are being displayed within the vehicle and this is being associated with the external temperature sensor within the exterior rear view mirror housing.

Action: Retailers should review the diagnosis and testing instructions within the Work Shop Manual first. This can be found under:

- 5: Body and Paint
- 501: Body and Paint
- 501-09: Rear View Mirrors
- Diagnosis and Testing
- Rear View Mirrors

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.