

LTB01055NAS1

TECHNICAL BULLETIN

26 MAY 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

206-04: Rear Disc Brake

SUBJECT/CONCERN:

Squeal Noise From Rear Brakes

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015 Onwards	500012 Onwards	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

A squeal noise may be evident from the rear brakes during light application of the brake pedal.

CAUSE:

During certain conditions, the friction of the rear brake system can cause a high frequency noise during light application of the brake pedal.

NOTE:

Make sure that this bulletin is applicable only to vehicles with the listed concern. Use of the listed parts listed to address any concern than that listed may cause greater Customer dissatisfaction. An example of this noise may be found in Special Service Message SSM73150 in GCM, reference noise type 2.

ACTION:

Should a Customer express this concern, follow the Service Instruction below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR095295	Rear Brake Pad Kit	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Pads - Rear - Set - Renew	70.40.03	0.6	42	LR061385

NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

- 1 Replace the rear brake pads (see TOPIx Workshop Manual section 206-04: Rear Disc Brake - Brake Pads).