



SERVICE BULLETIN

Classification: HA17-005a	Reference: NTB17-046a	Date: June 27, 2017
------------------------------	--------------------------	------------------------

2016-2017 TITAN AND TITAN XD; A/C COMPRESSOR SERVICE INFORMATION

This bulletin has been amended. The Title and APPLIED VEHICLES section have been revised. No other changes have been made. Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2016 - 2017 Titan and Titan XD (A61)
APPLIED VIN: 2016: All
 2017: Vehicles built before 1N6(*)A1(***)HN 515871
APPLIED DATE: Vehicles built before October 31, 2016

SERVICE INFORMATION

If the A/C compressor of an **APPLIED VEHICLE** is replaced for any reason, perform the existing procedure, **Oil Adjusting Procedure for Compressor Replacement**, in the applicable Electronic Service Manual, section **HA-Heater & Air Conditioning System**, and then add an additional 70 ml (2.4 oz) of compressor oil into the new compressor through the suction port opening.

NOTE: Check vehicle service history to confirm compressor replacement and oil addition was not previously performed. If the compressor was previously replaced and 70 ml of additional oil was added, perform **Oil Adjusting Procedure for Compressor Replacement** only (do not add any additional amount of oil).

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.