



Service Bulletin

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) On, DTC P11CC Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2016				2.8L (RPO LWN)	
GMC	Canyon						

Condition	Some customers may comment on the Malfunction Indicator Lamp (MIL) being illuminated. Technician may find DTC P11CC set.
------------------	---

Correction

A revised calibration has been developed to address this concern. Update the ECM with the latest calibration using the Service Programming System (SPS).

Service Procedure

Follow programming procedure instructions in K20 Engine Control Module: Programming and Setup in SI.

Warranty Information

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	0.4 hr

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION