



August 2017

BTS 170801 Version 1

Navigation Screen Clock Reads 00:00

AFFECTED VEHICLES

2001–03 CL, 2001–02 MDX, 2000–03 RL, and 2000–03 TL

Is the navigation screen clock reading **00:00**? We're aware of this issue and are looking for a solution.

Until then, **do not** replace any components. Doing so **won't** fix this issue.

© 2017 American Honda Motor Co., Inc. – All Rights Reserved