
Reference SSM73047

Models F-TYPE / X152

Title X152 - Clutch Kit Improvement - Updated Part

Category Driveline

Last modified 27-Mar-2017 00:00:00

Symptom 506000 Clutch Concerns

Content **Issue**
Premature clutch wear and poor clutch pedal feel

Cause
Clutch slippage between gear changes at high engine speed/torque.

Action
New parts are now available to order through EPC (Electronic Parts Catalogue) for this issue.

F - Type (X152) **New part number T2R27466** original part numbers T2R21165 & T2R25681

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.