

<b>Reference</b>	SSM73301
<b>Models</b>	F-PACE / X761 XE / X760 XF / X260
<b>Title</b>	AJ200D Oil level check at PDI
<b>Category</b>	Engine
<b>Last modified</b>	28-Mar-2017 00:00:00
<b>Symptom</b>	401000 Oil System Concerns

**Content**      **Issue:** AJ200D - Engine oil level shows a lower reading than the maximum mark on the oil level indicator.

**Cause:** Variability of tolerances within the engine is resulting in some engines indicating an oil level lower than the maximum mark on initial fills.

**Action:** PDI only:

- If the oil reading is below the max mark (within 5mm) - Please do not fill to the maximum oil level indicator as the quantity of oil in the engine is already correct.

Thank you for your assistance in this matter.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.