

# Technical Service Bulletin



## 44 Tire vibration (with originally-installed 245/40 R18 93H Pirelli P6 Four Seasons tires) - Repair Authorization

44 16 58 2043218/1 February 5, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 Cabriolet	2016	All	originally-installed 245/40 R18 93H Pirelli P6 Four Seasons tires

## Condition

- Customer may report feeling a vibration while driving at highway speeds.
- This Repair Authorization bulletin only applies to vehicles that meet the following criteria:
  - Vehicle is within the Adjustment coverage period (up to 12/12)
  - Vehicle has originally-installed 245/40 R18 93H Pirelli P6 Four Seasons tires
  - Tires have tire marking: AO
  - Vehicle has PR code: HM3

## Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the topic for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

## Production Solution

No changes to production have been made, as no issue has been identified.

## Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify the condition.
2. Complete the attached Tire Data Sheet, but *do not* perform any adjustments at this time.
3. Attach the Tire Data Sheet to the TAC ticket and contact a TAC consultant before proceeding.

# Technical Service Bulletin

---



## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Additional Information

All parts and service references provided in this TSB (2043218) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.